


SHMS Aerogel Update
10/4/2017

Overnight run #1204 (standard settings)




Actions made:


- 1) Discovered that ch#6(negative) was noisy (Main contribute to additional P.E. peak in spectra).
- 2) Checked with the scope ch#6 and other channels. No visible problems.
- 3) Swapped bases for ch#6 and ch#7 (both negative) and took a short cosmic run.
- 4) Problem disappeared, the bases swapped back, took overnight run.
- 5) At the next day morning ch#6(neg) shown the same behavior. Also ch#1(pos) and ch#5(pos) appeared to be noisy.
- 6) HV cables swapped for the bases.
- 7) The nominal voltages changed using HV GUI for swapped channels so the PMT got same HV as it should be.
- 8) During that operation noticed that HV module had strange behavior.
 - (Example: the voltages "flow" for few or tens of volts around nominal value)
 - This behavior did not disappear after software and hardware reboot of HV crate
 - Another detectors that connected to another HV card in the same crate looked normal
 - Spare HV card was found (CAEN Mod.A1535SP Ser.n 597)
 - SHMS aerogel HV connected to the spare card
 - HV Ch#0 and Ch#7 connected to output #14 and #15 (outputs #0 and #7 not working)
 - Checked that all HV works.
 - Set the software and hardware voltage Maximum
 - Put hardware interlock to card CAEN Mod.A1535SP Ser.n 587 (previous one)
- 9) Cables checked with pulser.
- 10) Started new overnight cosmic run.
- 11) Discovered no changes in spectra (noise, additional P.E. Peaks).
- 12) Set HV 50V below nominal-----> No changes.
- 13) Turned off HV for rear PMT`s at the TOF plane----> No changes.
- 14) Took overweekend run.
- 15) Unfortunately the run was corrupted because of DAQ problems.

PMT#6(Negative) could cause the problem itself ?

Ch#5 Negative




Ch#6 Negative




With Eric's help new version HCANA was installed.

BOOM!

Old analyzer version




Current analyzer version




same short cosmic run 1227

Eric : “ FlashADC 250 decoder had problem in old version of Analyzer.
Some pedestals was corrupted and have not been subtracted.”


SHMS Aero+ Good Pulse Time vs. PMT Number




SHMS Aero- Good Pulse Time vs. PMT Number






SHMS Aero+ Good Pulse Amplitude vs. PMT Number



SHMS Aero- Good Pulse Amplitude vs. PMT Number





Conclusions:

- 1) Total P.E. Spectra looks good with new analyzer
- 2) Ch#6(Negative) still questionable

Could the change of this PMT with spare before physic run solve problems ?
- 3) Need long (2 day) run to figure this out