# VXM Program Stored Commands

#### Motor commands: Set steps to incremental Index motor CW (positive), m= motor# (1,2,3,4), x=1 to setDMx **ImMx** 16,777,215 Set Analog Joystick Deadband value setDAx ImM-x Set steps to incremental Index motor CCW (negative), m= motor# (1,2,3,4), x=1 setjmM Set first Jog Speed setting for motor m to 16,777,215 setjAmM Set first Analog Joystick range setting for motor m IAmMx Set Absolute Index distance, m=motor# (1,2,3,4), x= ±1 to ±16,777,215 steps Set second Jog Speed setting for motor m setJmM **IAmM0** Index motor to Absolute zero position, m=motor# (1,2,3,4) setJAmM Set second Analog Joystick range setting for motor m **IAmM-0** Zero motor position for motor# m, m= 1,2,3,4 Set limit switch mode for axis m setLmMx ImM0 Index motor until positive limit is encountered, m=motor# (1,2,3,4) ImM-0 Index motor until negative limit is encountered, m=motor# (1,2,3,4) I setPmMx Set "Pulse Every x # Steps" on output 2 for axis m (i3,i1...) Combine Index commands to run simultaneously on two VXM controllers connected by VXM bus

**SmMx** Set Speed of motor (70% power), m= motor# (1,2,3,4), x=1 to 6000 steps/sec.

SAmMx Set Speed of motor (100% power), m= motor# (1,2,3,4), x=1 to 6000 steps/sec.

SmM-x Read and assign analog input value to motor m speed (70% power), x= range SAmM-x Read and assign analog input value to motor m speed (100% power), x= range

**AmMx** Acceleration/deceleration, m= motor# (1,2,3,4), x=1 to 127.

## Looping/branching commands:

- Loop continually from the beginning or Loop-to-marker of the current program L0
- Sets the Loop-to-marker at the current location in the program LM0
- Resets the Loop-to-marker to the beginning of the current program LM-0

### Lx Loop from beginning or Loop-to-marker x-1 times (x=2 to 65,535), when the loop reaches its last count the non-loop command directly preceding will be ignored Loop from beginning or Loop-to-marker x-1 times, alternating direction of motor L-x

- 1, when the loop reaches its last count the non-loop command directly preceding will be ignored
- Loop Always from beginning or Loop-to-marker x-1 times (x=2 to 65,535) LAx
- LA-x Loop Always from beginning or Loop-to-marker x-1 times, alternating direction of motor 1 LM-2 Loop once from beginning or Loop-to-marker reversing index direction of motor 2
- LM-3 Loop once from beginning or Loop-to-marker reversing index direction of motor 1 and motor 2
- Jx Jump to the beginning of program number x, x = 0 to 4
- **JMx** Jump to the beginning of program number x and come back for More after program x ends, x=0 to 4
- JM-x Similar to JMx except automatically moves back from absolute indexes after program x ends: For pick-and-place within matrix looping patterns

## Pausing commands:

- Pause x tenths of a second, (x=0 to 65,535) Px
- Pause x tenths of a millisecond, (x=1 to 65,535) P-x
- Pause x tenths of a second (x=0 to 65,535, 10 µsec pause when x=0) Altering PAx
- output 1 high for duration of the pause, tenths of a millisecond when x is negative Pause x tenths of a millisecond (x=1 to 65,535) Altering output 1 high for duration PA-x of the pause

### Input/output commands:

- Wait for a "low" on user input 1 **U0**
- Wait for a low on user input 1, holding user output 1 high while waiting **U1**
- **U2** Enable Jog mode while waiting for an input
- Disable Jog mode while waiting for an input **U3**
- User output 1 "low" (reset state) **U4**
- **U5** User output 1 high
- Send "W" to host and wait for a "G" to continue **U6**
- **U7** Start of Continuous Index with pulse on output 2
- U77 Start of Continuous Index with no output
- Start of Continuous Index sending "@" to the host **U8**
- End of Continuous Index with auto-decel to stop **U9 U91**
- End of Continuous Index with auto-generate a deceleration Index as next command
- 1192 End of Continuous Index using next Index for deceleration to stop
- **U99** End of Continuous Index with instantaneous stop
- Skip next command if input 1 is high **U11**
- Skip next command if input 1 is low **U21 U12** Skip next command if input 2 is high
- Skip next command if input 2 is low **U22**
- **U13** Wait for a front panel button to jump to a program or continue: "Motor 1 Jog -" button to jump to program #1, "Motor 1 Jog +" button to jump to program #2, "Run" button to proceed in current program.
- **U14** User output 2 low (reset state) **U15** User output 2 high
- Optional User output 3 low (reset state) U16
- Optional User output 3 high **U17**
- **U18** Optional User output 4 low (reset state)
- Optional User output 4 high U19
- Wait for a front panel button to jump to a program and come back, or continue: **U23** "Motor 1 Jog -" button to jump and return to program #1, "Motor 1 Jog +" button to jump and return to program #2, "Run" button to proceed in current program
- Wait for a low to high transition on user input 1 **U30**
- Wait for a low to high transition on user input 1, holding user output 1 high while **U31** waiting
- **U32** Wait for "Motor 1 Jog -" button to be pressed on front panel with debouncing
- Wait for "Motor 1 Jog +" button to be pressed on front panel with debouncing **U33**

- VXM Set Commands
- setMmMx Set axis m for motor type/size x (see table below for value for x) Set VXM/VP9000 or NF90 emulation modes, and other operating parameters setPAx Set Pulse width used by setPmMx and U7, x=1 to 255 (10 µsec increments) I Set operating mode of inputs setlx Set RS-232 Baud rate (9=9600, 19=19200, 38=38400) setBx Backlash compensation, x=0 to 255, 0= off (default), 1= 20 steps Bx Indicate limit switch Over-travel to host, off when x=0, VXM sends "O" when x=1 Ox I and hit limit, x=3 program stops too Program Associate program x in Master to program x in Slave (Linked VXMs **PMAx** I start the same time) (255= default/disabled) . \_ . \_ . \_ . \_ . . VXM Immediate Commands **Operation commands:** С Clear all commands from currently selected program D Decelerate to a stop (interrupts current index/ program in progress) Е Enable On-Line mode with echo "on" F Enable On-Line mode with echo "off" G Enable On-Line mode with echo off Grouping a <cr> with "^", ":", "W", "O" responses; Also Go after waiting or holding Н Put Controller on Hold (stop after each command and wait for go) Κ Kill operation/program in progress and reset user outputs Ν Null (zero) motors 1,2,3,4 absolute position registers Quit On-Line mode (return to Local mode) Q R Run currently selected program Record motor positions for later recall with "x","y" commands 1 Run save memory (saves setup/ program values to nonvolatile memory) rsm Software reset controller res del Delete last command Send data to Slave through Master (two VXM controllers [i1,i2...] connected by VXM bus) setD0 Set VXM back to factory defaults (All programs, settings, motor selections will be erased) **PMx** Select Program number x, x= 0 to 4 PM-x Select and clear all commands from Program number x, x= 0 to 4 Status request commands: Verify Controller's status, VXM sends "B" to host if busy, "R" if ready, "J" if in the V Jog/slew mode, or "b" if Jog/slewing X Y Send current position of motor 1 to host (Motor can be in motion) Send current position of motor 2 to host (Motor can be in motion) Ζ Send current position of motor 3 to host (Motor must be stationary) Т Send current position of motor 4 to host (Motor must be stationary) Μ Request Memory available for currently selected program List current program to host (ASCII text) lst х Send last 4 positions of motor 1 to host that were captured by the "!" command or Input 4 trigger Send last 4 positions of motor 2 to host that were captured by the "!" command or У Input 4 trigger # Request the number of the currently selected motor \* Request the position when the last motor started decelerating (shows position when "D" command or Stop/User input 4 used) ? Read state of limit switch inputs for motor 1 and 2 (8 bit binary value) Read state of User Inputs, Motor 1 and 2 Jog Inputs (8 bit binary value) \$ Read state of User Outputs (8 bit binary value) @ Read user analog input value В Read Backlash compensation setting 0 Read Indicate limit switch setting D Read/Digitize motor position (Jog Mode) Request the number of the current Program ΡM Request the current program associate number (255= default/disabled) **PMA** getMmM Read motor type/size selected for axis m Read operating mode of VXM getDM Gets the VXM's firmware version in the format X.XX getD0 getD1 Gets the VXM's firmware date code in the format XX-XX-XX (month,day,year) getD2 Returns 2 if system is a single VXM, returns 4 if VXM is a Master Read Analog Joystick Deadband setting getDA getjmM Read first Jog Speed setting for motor m
  - getjAmM Read first Analog Joystick range setting for motor m
- getJmM Read second Jog Speed setting for motor m
- Wait for a low and high on user input 1 with debouncing for a mechanical push button switch
- U51 Wait for a low and high on user input 1 with debouncing for a mechanical pushbutton switch, holding user output 1 high while waiting
- Wait for a low to high on the Run button or connection I/O,4 with debouncing for **U90** a mechanical push-button switch





Lead S	crew Models	<b>D</b> :011 1 11			Speed
Un	iiSlide*	BiSlide**	Advance per turn	Advance per step	@ 1000 SPS (2.5 rev/sec)
			Units	Units	Units
С	P40	E25	0.025 inch	0.0000625 inch	0.0625 inch/sec
В	P20	E50	0.05 inch	0.0001250 inch	0.125 inch/sec
W1	P10	E01	0.1 inch	0.0002500 inch	0.25 inch/sec
W2	P5	E02	0.2 inch	0.0005000 inch	0.5 inch/sec
W4	P2.5	E04	0.4 inch	0.0010000 inch	1 inch/sec
K1	Q1	M01	1 mm	0.0025 mm	2.5 mm/sec
K2	Q2	M02	2 mm	0.0050 mm	5 mm/sec
Rotary	Tables				

	Gear Ratio			
B4872	72:1	5 degree	0.0125 degree	12.5 degree/sec
B4836	36:1	10 degree	0.0250 degree	25 degree/sec
B4818	18:1	20 degree	0.0500 degree	50 degree/sec
B5990	90:1	4 degree	0.0100 degree	10 degree/sec
* Typical UniSlid	le model (where x is from abo	ove table): MB4024xJ-S4		

To convert from "real" units to steps, divide the distance desired to move by the Advance per step. (Distance ÷ Advance per step = Steps)

getJAmM Read second Analog Joystick range setting for motor m getLmM Read mode of limits for motor m getPmM Read "Pulse Every x # Steps" value for axis m Read Pulse width used by setPmMx and U7 getPA

2

3

4

5

6

7

9

Read operating mode of user inputs getl

x	Motor Model (Amps)
0	Default (0.4A to 0.7A)
1	Vexta PK245 (1.2A)
2	Slo-Syn M061 (3.8A)
3	Slo-Syn M062 (4.7A) Vexta PK264 (3A)
4	Slo-Syn M063 (4.6A) Vexta PK266 (3A)
5	Slo-Syn M091 (4.7A) Vexta PK268 (3A)
6	Slo-Syn M092 (4.6A)

- Pin# Name 0V +5V Ain I/O Run 11 12 10 • • • • • • • 6 13 8 14 • • • • • 14 13 12 11 0V 15DSUBHD Socket 10 J1-11 J1+ 12 J2-13 J2+ 01 14 15 02
- Phone: 585-657-6151 and 800-642-6446 585-657-6153 Fax: info@velmex.com Email: Internet: www.velmex.com and www.bislide.com 7550 State Route 5 & 20 mail:



12-29-04

Document # VXM-CS VXM Version 1.30