

Salim Roustom

Setting Up the PMT Testing Configuration

- I set up the High Voltage on Monday
- I now need to set up the signal input
- Once the input is setup, I will test the old PMTs to see which are dead, and try to test the dead ones for Helium
- If they are dead, then I will remove them from their cases and install new ones

Research on the Effect of Helium on PMTs

- I have found a paper that outlines the effect of Helium on PMTs
- I must now find how to test for Helium in the PMTs